

General Environmental Incident Summary

Incident: 3299 **Date/Time Notice:** 4/25/2014 08:30a **DEM Incident No:**
Responsible Party: Wolf Trucking

Date Incident: 4/25/2014 **Time Incident:** 08:30am **Duration:** 10 minutes

County: Ward **Twp:** 156 **Rng:** 49 **Sec:** 21 **Qtr:** SE SE SE

Lat: 48.32466 **Long:** -101.75070 **Method:** Interpolation from map

Location Description: 8501 296th St. N.W. Berthold, ND 58718
Unloading Lact Unit

Submitted By: Daniel Glowatz **Affiliation:**

Address: 3773 Cherry Creek North Dr.

City: Denver **State:** CO **Zip:**

Received By:

Contact Person:

Berthold
Berthold , ND

Distance Nearest Occupied Building: 15 Miles **Release Contained:** Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Crude Oil

Volume Spilled: 1.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Employee pulled up to unload and when he left he failed to shut off the bleeder valve causing about a barrel or a little less to spill.

Risk Evaluation:

No it was cleaned up immediately

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil about 6 inches deep. It was cleaned up immediately. About a half barrel was spilled on the ground.

Action Taken or Planned:

He requested a report from the 3rd party company. We are working with them to ensure there is procedures put in place to make sure this does not happen again.

Wastes Disposal Location: At a facility disposal unit. The third part company will have paper work on where the waste is going.

Agencies Involved: Company

Updates

Date: 4/28/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary this spill impacted areas that are not associated with a NDIC facility. Follow up is necessary.

Date: 6/3/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Volume:

Notes:

Inspected site 06/03/15. No sign of impact remains, and it does appear to have been cleaned up promptly as indicated on spill report.